

# CONVERSION CHART HEMP (CANNABIS SATIVA)

## F-2000 HAY MOISTURE METER

F-2000 READINGS	% MOISTURE CONTENT
7	7
8	7.5
9	8.5
10	9.5
11	10
12	11
13	11.5
14	12.5
15	13.5
16	14
17	15
18	16
19	16.5
20	17.5
25	21.5
30	25.5
40	34

Above readings taken with equipment as follows:

Meter: F-2000

Electrode: H-4 & 831 Prod

**NOTES -** Readings rounded to nearest 0.5 - use as a guideline

For best results, use a 1 quart teflon container & fill to the top.

Press the electrode (H-4 with 831 prod) into the material until it compresses to 1/3 the volume. Take the reading. Take several readings for an average.

Delmhorst Instrument Co

[www.delmhorst.com](http://www.delmhorst.com)

[info@delmhorst.com](mailto:info@delmhorst.com)

Feb-19